


Lazo Road – Town of Comox

Infrastructure Notes

COMOX VALLEY CYCLING COALITION

NOVEMBER 2020

<u>Lazo Loop – Locator Map</u>



- Busy roadway Highly used by recreational cyclists, commuters to airport, and vehicles
- Two serious cycling incidents reported to CVCCo in 2020

<u>Camox Section</u> – approx. 1.6 km on **Lazo Rd** between Simba and Kye Bay Rd

<u>Lack of Shoulder – Lazo Road</u>



- Streetview of westbound Lazo Rd near Southwind Rd (Pt Holmes)
- No paved shoulder for cyclists.
 Gravel on shoulder and parking lot is in poor condition and unsafe for cyclists
- High vehicle traffic area also with vehicles parking for Pt Holmes (backing out onto roadway)

Dangerous Conditions on Lazo Road



- Views of westbound Lazo Rd
- Sharp edge on shoulder is a severe hazard to cyclists
- Blind corner with no room for error by vehicles or cyclists

Recommendations

- Add appropriate paved bike accessible shoulder to both sides of Lazo Road from Simba Road to Kye Bay R
- Coordinate work with MoTI so they can also add shoulders to Knight Rd from Kye Bay Rd to Airport
- Install no passing signage and line paint at portions of this route where vehicles often turn or near parking areas at Point Holmes