

Seal Bay (Bates and Coleman Road) Infrastructure Notes

COMOX VALLEY CYCLING COALITION
OCTOBER 2020

Seal Bay-Locator Map

Kitty Coleman
Beach
Provincial
Park

ColemanRd

ColemanRd

Bates Road


So 8 min
2.6 km

Coleman Road – approx. 2.6 km from Bates Roat to intersection of Left Rd

Grantham

- Very busy roadway Highly used by recreational cyclists, commuters to ferry, and vehicles
- Bates Road passes through Seal Bay Nature Park
- Main route from ferry terminal to Campbell River and north island destinations

- Total of 6.5 km that requires sl COALITION upgrades/paving
- Broken into two sections for presentation
- Speed limits of 70 km/h (Bates) and 80 km/h (Coleman)



<u>Poor Shoulder – Bates Road</u>

- Shoulders on Bates Rd are either nonexistent or unpaved and dangerous for cyclists
- Speed limit is 70 km/h
- Poor visibility, very shaded in spots





Bates Rd near Waveland Rd

<u>Bates Road – North of Seal Bay Park</u>





Bates Rd near Anson Rd

<u>Coleman Road – Bates to Left Road</u>

- No Shoulders on Coleman Rd from Bates Rd to Left Rd intersection
- Speed limit is 80 km/h
- Poor visibility due to shading and corners



<u>Coleman Road – Between Left Rd and 19A</u>





- Westbound shoulder is ok, but eastbound needs to be widened
- Speed limit is 80 km/h

<u>Seal Bay Parking Lot – Bates Rd</u>





- Bates Rd passes through Seal Bay Nature Park (SBNP)and there is a wellused parking lot adjacent to the roadway
- SBNP is popular with nature lovers, hikers, dog walkers, runners and cyclists
- Dangerous situation at parking area with high speed traffic (70 km/h) and no shoulders

Seal Bay Parking Lot – Crossing of Bates Rd





- There are two trails at the parking lot which require pedestrians to walk across Bates Road to access
- Again, a very Dangerous situation at parking area with high speed traffic (70 km/h) and no crosswalk, signs or traffic calming

Recommendations



- Immediately reduce speed limits from 70 and 80 km/h to 50 km/h on Bates Road and the portion of Coleman Rd where shoulders are not adequate.
- Install no passing signage/line paint and marked crosswalks with signs at the Seal Bay Bates Road parking lot.
 Traffic must be calmed through this parking area or there is high risk of a serious accident.
- Widen (as necessary) and pave shoulders on Bates
 Road
- Add appropriate paved bike accessible shoulder to both sides of Coleman Rd from Bates Rd to Left Rd
- Widen eastbound shoulder of Coleman Rd from Hwy 19A to Left Rd